SP/SSW	/ EMD SD45T-2 A	s-Delivere	d Detail Gu	ide					
247 total uni									
	dwin C. Cooper; detail n	natrix added by I	Harry K. Wong -	Additions/corrections v	velcome				
	d 2/21/2005		lany ra trong						
Class	Road Number	Refer to note #	Date Blt	Snowplows	Anticlimber	Bell Location	A/C	antenna	jacking pad
EF636C-6	SSW 9157-9165	A	Jul-72	DW140 Front only	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636-7	SP 9166-9220	A, B	Feb-Apr-72	DW140 F&R	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636-8	SP 9221-9240	Α	Apr-May 72	DW140 F&R	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636-9	SP 9241-9260	A	May-Jun-72	DW140 F&R	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636C-7	SSW 9261-9281	A	Feb-73	DW140 Front only	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636C-8	SSW 9282-9301	A	Mar-73	DW140 Front only	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636-10	SP 9302-9313	A	Sep-73	DW140 F&R	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636-11	SP 9314	A, B	Apr-74	DW140 F&R	tapered	rooftop centered	none	whip - RA1802	std EMD
EF636-12	SP 9315-9329	С	Jan-Feb 74	DW140 F&R	tapered	atop numberboard - conductor side	yes	sinclair on table	std EMD
EF636-12	SP 9330-9343	C, E	Jan-Feb 74	DW140 F&R	Full Width Large	atop numberboard - conductor side	yes	sinclair on table	std EMD
EF636-13	SP 9344-9355	C, E, F	Jan-Feb 75	DW140 F&R	Full Width Large	atop numberboard - conductor side	yes	sinclair on table	std EMD
EF636-13	SP 9356-9370	C, E, F	Jan-Feb 75	DW140 F&R	Full Width Large	atop numberboard - conductor side	yes	sinclair on table	std EMD
EF636C-9	SSW 9371-9404	C, D	Mar-Jun 75	DW140 Front only	Med. Width Large	atop numberboard - conductor side	yes	sinclair on table	SP 4-hole
Notes:						1	1	- 1	1
	ivered with full L-shaped			d pyle headlight only or	rear hood.				
A - Units de	livered w/o A/C also feat								
				<b>v</b> 1	cab roof section - firema	in's side			
			ed near-center c						
			na mounted on						
				ally above engineer's L					
-			ounted vertically	/ on engineer's side rea	ar cab door.				
B - 9220 wi	recked and rebuilt as the	9314							
			l <u>.</u>						
C - Other te	atures compulsory on ur				line and a side of a sh				
				berboard on conductor		tandad braakat			
					eers side of cab on an ex			of each)	
						d area to atop the electrical cabinet (ne atop front of inertial filter behind cab roo			
						m numberboard assembly to the sinclai			
				<b>v</b>		In numberboard assembly to the sinclai ulting in the disappearance of the louver		h wall in front of the	onginoor
				also received	electric cap rieaters, res		s on the ca		engineer.
D - 26/1/ 03	89 was delivered in Bice	ntennial paint on	d was the 600th	3600 horsenower EM	D on the SP system				
	SSW 9389 also was equ				D on the or system				+
					ler cut levers circa 1977.				-
						stanchions adjacent to the gangway is	not precise!	v known The desig	n change occ
References	Boster complied by Er	win C. Cooper	Details compiler	hy Harry Wong from t	he following sources: "EN	/ /ID SD45T-2 Tunnel Motors", Brian Ruth	perford Die	sel Fra Magavine, M	lav/June 1001
vereiendes	. Roster complied by Et	awin C. Cooper,	Details complied	ו ווטווע געטווא איטווא ווטווו נ	The following sources. El	Diali Ruli	ienoru, Die	sei Lia iviayaxille, iv	ay/June I

double									
stanchions on									
rear									
anticlimber									
single only									
single only									
single only									
single only									
single only									
single only									
single only									
single only									
single only									
single only									
single only									
double									
double									
			<u> </u>						
red somewhere between 9353 and 9359.									
and from photos	on espee.ra	ailfan.net							